






LEGEND

-  MONITORING WELL
-  GROUNDWATER EXTRACTION WELL
-  DESTROYED MONITORING WELL (DECEMBER 1992)
-  WELL PAVED OVER

NOTE: SITE MAP ADAPTED FROM DELTA ENVIRONMENTAL FIGURES.
SITE DIMENSIONS AND FACILITY LOCATIONS NOT VERIFIED.



URS

Project No. 38486309
Arco Service Station 0362
29900 Mission Boulevard
Hayward, California

SITE MAP